Safety Instructions

In order to prevent your **PANRAN** products from being damaged or to avoid injury to you or others, please finish reading these following safety instructions before you operate this instrument. And put the safety instructions within reach, please .

The consequences which may be caused by not following the precautions we enumerate in this chapter are marked with the following symbols.



The symbol indicates a warning which requests you to read the information before using the product to prevent possible damage.

Warning

Please press the button"reset" quickly in the process of verification when abnormal situation encounters. (PR9120Y, PR9120Q Only)



Please press the button "reset" on the side of the chassis quickly in the process of pressure rising and falling when abnormal situation encounters(for example: abnormal sound,uncontrolled motor, high over-voltage).

You must tighten up the joint to avoid pressure leaking when it is joined up to the gauge to be tested.



You can use a spanner to help tighten up to the gauge to be tested when necessary.

The oil(water) in the oil(water) cup must not exceed the mark (PR9120Y Only).



It may spill over out of the the pressure outlet, if there is too much oil.

Do remember to turn off the power after turning off the controlling computer.



Do remember to cut off the outer power after the computer are turned off.Or the main parts of the instrument are still in Power.



The outer power cord must be plugged into a grounded outlet correctly.

Notice

- The content of the manual attached to the instrument mustn't be reprinted or disseminated in any way without prior written permission from PANRAN company.
- Our company reserves the right to amend the information of the manual at any time without prior notice.
- We refuse to take any responsibility for the damage of using the product .
- We must do everything in our power to ensure accuracy and perfection of the manual information, if you find any mistake or omission, please call our customer service staff and we will be indeed very grateful.

After sales special line:17662527586

E-mail: pryl@panran.com

Catalogue

Safety instructions1
Notice2
Catalogue3
I. Function description4
II.Application4
III.Features4
IV.Main technical parameters and composition5
V.Introductions7
VI.Verification operation14
VII.Routine maintenance21

I.Function description

PR9120Y/Q/W automatic pressure generator, which adopts high speed AD, high performance servo motor and controller, has been researched and developed by software control technology combined with the latest algorithm. It has stable pressure and fast speed, and its control precision can reach one in ten thousand which very much meet the needs of enterprise's periodic mass repetitive measuring calibration work. Full automatic control,14 inches touch screen, software layout design with comprehensive functions does not make verification of pressure gauge difficult any more but brings you to enjoy the relaxation and pleasure brought by high -tech equipment.

II.Application

It is used to verify or calibrate general pressure gauges, precision pressure gauges, electric contact pressure gauges, pressure switches , pressure transmitter and some other pressure related instruments.

III.Features

1. The speed controlling is fast . The pressure reaches the set point for less than 30 seconds.

2. The pressure is fast and stable, which conforms to the verification regulation of relevant pressure instruments.

3. The host machine can change multi range PR9111 or PR9112 intelligent pressure calibrator to improve the measurement accuracy and periodic verification convenience.

4. The instrument with 14 inches touch screen, built in control software can get more stable operation and support remote maintenance and software upgrade.

5. The device can print the certificate with the printer directly .

6.With wireless module, it can support remote assistance after networking and remote upgrade management ,etc.

7.It can change certificate template and support certificate exporting according to customer requirements. (PDF format).



IV Technical parameters



PR9120Q parameters and composition

- Pressure range: (-95~600) kPa
- Working medium:Air
- Pressure control fluctuation<0.005%F.S</p>
- Overall dimension: 545mm × 370mm × 350mm
- Weight:20kg



PR9120Y parameters and composition

- Pressure range : (-0.04~0~60) MPa
- Working medium: transformer oil ,purified water
- ◆ Pressure control fluctuation <0.005%F.S
- Overall dimension: 660mm × 370mm × 410mm
- Weight: 30kg



PR9120W parameters and composition

- Pressure range: (-40~40) kPa
- Working medium:Air
- Pressure control fluctuation<0.005%F.S</p>
- Overall dimension: 545mm × 370mm × 350mm
- Weight:13kg

V.Introductions

1.Power on

Access to 220 v power supply ,turn on the switch on the power socket and the device will start and enter loginnig interface automatically;



User name : admin, password: admin (you can change it in the management of inspectors)

2.Introductions of software interface

2.1 "green" indicates the current running state;



2.2 External standard device (PR9111 or PR9112) for synchronous data display;



2.3 Set target pressure value, use your finger or the mouse to click the digital part ,the interface of value will appear;



Voltage: 0.0000 SW Status Switch : 0.0000 OFF	Number Pad
Target Pressure	0.0000
0.0000	7 8 9 Del
MPa	4 5 6
RUN T	ОК
2021-10-09 15:01:23	
	0 . +/- C
Calibrator Information	

2.4 Information of external standard instrument;

Calibrator	Information
Range:	0 ~ 700 bar
Name :	Class:
Model:	Media:
NO. :	Valid:

2.5 Click to close the system;

Shutdown	🛛 🦲 Keset

A prompt will appear:



1)"Yes":exit from the software and turn off the computer at the same time.and then shut off the host engine by hand;

2)"No":return to the computer desktop,you can enter administration software once again through the shortcut icon of the desktop software;

2.6 Function option menu;



2.6.1 New verification

Add New Instrument	~	
100	Туре	Normal Pressure Gauge
and and a second	Name	•
+	Model	•
	Number	•
	Range	(0 • ~ 1 •) MPa •
η μ	Grade	1 • Division •
E /	Check Points	5
	Manufacturer	•
	Department	•
	Contact Person	•
	Contacts Mobile	•
	Inspection Date	February -04-21
	Completion Date	February -04-21
	Inspection Number	·
		Mandatory Calibration
		× <u>C</u> ancel ✓ <u>O</u> K

Input the detailed information of the pressure gauge to be tested;

2.6.2 Instrument management

uery Unch	ieck) Checke	d				<u>sea</u>	arch	Operation	d 🛛	lodify	🙀 <u>D</u> elete	🎲 <u>C</u> heck	<u>■</u> <u>V</u> iew	Export
ormal	Pressur	e Gauge	Precision	n Press	sure Gau	ige	Digital Man	ometer	Pressure Transi	nitter Press	ure Switch	Flow Transmit	ter	elected 1	
Гуре	Name	Model	Number	Unit	Grade	Div	Low-Limit	Hi-Limit	Check Points	Mandatory	Humidity	Temperature	Manufacturers	Department	Contact Pers
					m										

Query the information of pressure gauge not checked and checked (It can be retrieved based on information such as the customer company, range, name, number, manufacturer and other information of the gauge to be tested) ,and you can modify ,delete ,test or preview it at the same time;

2.6.3 Management of standard instrument

PR9120Y/Q/W Automatic pressure generator

Name	Model	Number	Unit	Low	Hi Li	Manufact	Grage	Report N	Media	Effective date
🗑 Digital Pressure	PR9120	P0001	bar	0	700	Paran	0.05	CNP2020	Oil	2022-01-23
Effective		.		14 Pr						

You can add, modify or delete something with the standard instrument;

2.6.4 Management of certificate codes

10	Number Se	quence	0 0 0 00	
			Number Prefix	
	Norma	l Pressure Gauge	ptyl	- Date - Serial No
F	Precision	Pressure Gauges	jmyl	- Date - Serial No
	D	igital Manometer	szyl	- Date - Serial No
	Pre	ssure Transmitter	<mark>y</mark> lbs	- Date - Serial No
		Pressure Switch	ylkg	- Date - Serial No
	Format:		- Adverte	Cardal Na
		Header- V Year	[⊻] iviontn	-Serial INO.
		ptyl-	-202102-000	02
	Remark:			
D	Certificat	e Number: Prefix +	Year and Mo	nth + Serial No.
	The Carl	al No. starts to reco	ount every mor	nth.

1)Select "Custom Certificate Number", you need to manually enter the certificate number in the

pressure verification interface;

2)Click "Edit" to edit the certificate number prefix and certificate number format.

2.6.5 Management of inspectors

User List		🔇 Add New User
Admin User	Modify <u>Delete</u>	User Name: Password: Confirmation: User Rights: Common
	× <u>C</u> ancel	<u> О</u> К

Set a new inspector and the permissions;

2.6.6 Unit information

1	Company Name		
6	Company Address		
	FAX.		
	TEL.		
÷	Post Code		
	E-Mail		
0	Website		
59			[

Click "modify" to input unit information;

2.6.7 System maintenance(only for PR9120Y automatic pressure generator)

Exhaust / Sewage	×
1. Please connect the air(feculence) click the [Begin] key of the corres)-out port to the output port near the oil cup, sponding port and enter automatic process.
2. When there is no bubble or fecul confirm to click the [Stop] key of	lence discharging from the transparent tube, i the corresponding port to deal with the next port.
Egit	Begin 1 Begin 2 Begin 3

1)When the device appears "cannot pressurize" or "pressurize slowly" and it needs to exhaust air, please connect according to the requirements of this figure, connect the hose to the oil cup, and click Start;

2)When the pressure output port is blocked or the system needs to be drained, please connect according to the requirements of this figure, connect the hose to the container, discharge the contaminated medium, and click Start;

3)After exiting, remember to remove the hose, connect the plug or the gauge to be tested, and click the "reset" button in the lower left corner of the interface, otherwise the system will not work normally.

2.6.8 System setting



1)Instrument types:

1767		
	Oil Pressure	-
	Oil Pressure	

PR9120Q:choose "air pressure"

PR9120Y: choose "oil pressure"

PR9120W: choose "micro pressure"

2)Communication serial ports designating:

Click and choose corresponding options "test", and it will seek "communication serial ports" automatically. The tested result is following:





3)"Interface language": "Chinese, English" can be selected;

4) "Standard device level", according to the equipment equipped with "standard gauge (PR9111 or PR9112)" accuracy level selection, there are 0.02, 0.05, 0.1, 0.2, 0.5;

5)"Pressure controlling accuracy" can be chosen as "full scale accuracy 100%,75%,50%,25%",the smaller the numerical value is ,the higher the pressure controlling accuracy is ,the longer the stabilization time is;

6) "Test report directory", storage report path;

7)Manual input mode: Optional keyboard, selection items

(The keyboard is a numeric keyboard input mode, and the selection item is the pointer position selection input mode)

8)Check "Hide login window" and log in directly without entering a password;

2.6.9 Report catalogue

Open the storage certificate and record folder, you can search for files based on the year, month, and certificate name.

2.6.10 Using help

1)"Software registration": Enter the registration code to extend the use time (under normal use, you can't click "register" at will, otherwise the time will be cleared and the software function will be locked);

Software Registration	
Application code	
Registration code	

2) About": Open the software introduction;

3)"Help": open the device manual;

4)"Verification Regulations": general pressure gauges, precision pressure gauges, digital pressure gauges, pressure transmitters, pressure controller electronic version verification regulations.

VI.Verification operation

Eg1:Verification of ordinary pressure gauge(the operating method is the same as that of accuracy pressure gauge and digital pressure gauge)

1)Click "gauge management" and choose "ordinary pressure gauge";

Uncheck () Checked	n	Oper	ation	Mc	odify	elete	Check	View	Export	➡ <u>R</u> eturn]				
ormal Pressure Gauge Pre	cision Press	sure Gauge	Digital N	lanom	eter Pr	essure	Transmitte	r Pressu	re Switch Flow	v Transmitter		The specificati	ions are the sam	e and can be	
Туре	Name	Model	Number	Unit	Grade	Div	Low-Limit	Hi-Limit	Check Points	Mandatory	Humidity	Temperature	Manufacturers	Department	Contact Perso
🗏 Normal Pressure Gauge	NP-Series	NP-01M	N000101	kPa	1	0.05	0	60	7	0			PANRAN	PANRAN	
Nerenal Deserves Course	NP-Series	NP-02M	N000102	kPa	1	0.05	0	60	7	0			PANRAN	PANRAN	

2)Choose the gauge to be tested (the software can test two gauges in the same range at the same time)and click"calibration";

uery		- 6	O. Crush	Op	eration		utte Dinutus Caretus I	Man		Datum.	1
Oncheck O Che	cked		Search	L	- Add			View	<u>Cxport</u>	- Vernu	J
ormal Pressure Gau	ge Precision Pressure Gau	ge Digita	al Manometer F	ressu	re Transmitt	er Press	ure Switch Flow Transmitter Th	e specifica	ations are the sam	e and can be	
Туре	Name Model	Numb	er Unit Grade	Div	Low-Limi	t Hi-Limi	Check Points Mandatory Humidity Te	mperature	e Manufacturers	Department	Contact Perso
🛛 Normal Pressu 🤇	Select Standard Calibrator	-	10 Mar 1	-	1.0	-	3 8		×	PANRAN	
✓ Normal Pressu	Name	Model	Number	Unit	Low Limit	Hi Limit	Manufacturer	Grage	Report Number	PANRAN	
	🗒 Digital Pressure Gauge								RB21H-AD1037		
	🗑 Digital Pressure Gauge	PR9112	W2109C22006	kPa	0	40	Tai'an Panran Pressure Instrument Co., Ltd.	0.05	RB21H-AD1037		
	•	_		_	m				•		
	Effective							ant [Y Cancel		
	📅 Overdue						-	CAL			

3) Choose the standard gauge to be used (note that the range of the selected standard gauge

must be consistent with the range of the currently installed standard gauge).click "next";



4)Test system status, and click "ok" after confirmation;

5)Wait for about 10 seconds, the pressure is displayed as a non-zero state, click the "clear" button of the standard device (PR9111 or PR9112);



6)After the device prompts that it is stable, enter the data of the gauge to be tested in the "displayed value before tapping" form;

a)Click the first blank cell on the left side of the boost to display "pointer position selection" or "numerical keyboard", and enter data;

b)Then tap the gauge to be tested, enter the gauge to be tested data in the "Tap Value" form, the device will automatically jump to the next verification point and automatically increase the pressure (the following verification points have the same operation);



PR9120Y/Q/W Automatic pressure generator

tandard		Display b	efore tap		Display a	after tap	Pointer	displaceme	ent	Data Range	Upper(9	0-100)%	Others
	1	Up	🛉 Down	1	Up	🔶 Down	🛉 Up	¥ [Down	Max Re	turn Error		
0.00			_								Allowed	0.96	0.60
10.00										Max Dis	play Error		
20.00					0	Pointer Position	×			4	Allowed(±)	0.96	0.60
30.00						+5 0.05				Pointer dis	placement		
40.00						+4 0.04					Allowed	0.48	0.30
50.00					12	43 0.02							
60.00					12	0.03							
		-			12	•2 0.02							
UT Into			Operation		11	+1 0.01		-		Check Resul	ts		Calculation
Model: AA			Visual check	Pass		+0 0.00	10-0000	1		E	7		
lumber: AA			Zero position	Pass		-1 -0.01		-		C			
Grade: 1	uuu		Pointer offset	Pass		-2 -0.02		-					Save Data
Unit: ME	-		Humidity	50	~	-3 -0.03							
Onit: Wir	rd .		Insulation Res.	20	M	-4 -0.04							
						0.04							
erification N	ormal Pre	ssure Gau	ge	1									
erification N Standard	ormal Pre	ssure Gau Display	3e before tap		Displa	y after tap	Poiu	nter displac	ement	Data F	lange Upp	per(90-10))% Others
erification N Standard	ormal Pre	ossure Gau Display Up	ge before tap ∲ Down	+	Displa Up	y after tap ∲ Down	Poiu Poiu	nter displac	ement Down	Data F	lange Upp ax Return Er	per(90-10)	0)% Others
erification N Standard 0.00	ormal Pre	ssure Gau <i>Display</i> Up	ge before tap ∳ Down	+	Displa Up	y after tap ∳ Down	Poir	nter displac	ement Down	Data F	lange Upp ax Return Er Allov	per(90-10 rror wed 0.9	0)% Others
erification N Standard 0.00 10.00	ormal Pre	essure Gau Display Up	ge before tap ∲ Down	+	Displa Up	y after tap ∳ Down	Poir	nter displac	ement Down	Data F M	Lange Upp ax Return Er Allow x Display Er	per(90-10) rror wed 0.9 rror	0)% Others 6 0.60
erification N Standard 0.00 10.00 20.00	ormal Pre	ussure Gau Display Up	ge before tap ∲ Down	+	Displa Up	y after tap ∳ Down	Poiu	nter displac	ement Down	Data F M. Ma	tange Upp ax Return Er Allow x Display Er Allowed	per(90-10) rror wed 0.9 rror d(±) 0.9	0)% Others 6 0.60 6 0.60
erification N Standard 0.00 10.00 20.00 30.00	ormal Pre	ussure Gau Display Up	ge before tap ∲ Down	*	Displa Up	y after tap	Poiu	nter displac	ement Down	Data F M. Ma	lange Upp ax Return Er Allov x Display Er Allowed	per(90-100 rror rror rror d(±) 0.9	0)% Others 6 0.60 6 0.60
erification N Standard 0.00 10.00 20.00 30.00 40.00	ormal Pre	ussure Gau Display Up	ge before tap ∲ Down	*	Displa Up	y after tap Down		nter displac	ement Down	Data F M. Ma	tange Upp ax Return En Allow X Display En Allowed	per(90-100 rror wed 0.9 rror d(±) 0.9	0)% Others 6 0.60 6 0.60 8 0.30
erification N Standard 0.00 10.00 20.00 30.00 40.00 50.00	ormal Pre	Display Up	ge before tap ∲ Down	+	Displa Up	y after tap ↓ Down	Poin	nter displace	ement Down	Data F M. Ma .00	lange Upp ax Return Er Allov x Display Er Allowed	per(90-10) rror wed 0.9 rror d(±) 0.9	0)% Others 6 0.60 6 0.60 8 0.30
erification N Standard 0.00 10.00 20.00 30.00 40.00 50.00 60.00	ormal Pre	ussure Gau Display Up	ge before tap ∲ Down	^	Displa Up	y after tap ∳ Down	Point UI	Number Pad	ement Down	Data R Ma .00	Lange Upp ax Return Er Allower Allower	per(90-104 rror wed 0.9 rror d(±) 0.9	0)% Others 6 0.60 6 0.60 8 0.30
erification N Standard 0.00 10.00 20.00 30.00 40.00 50.00 60.00 WUT Info	ormal Pre	Display Up	ge before tap V Down Operation	*	Displa Up	y after tap	Point Point	nter displace	ement Down	Data F M Ma .00	lange Upr ax Return Er Allower Allower	per(90-104 rror wed 0.9 rror d(±) 0.9	0)% Others
erification N Standard 0.00 10.00 20.00 30.00 40.00 50.00 60.00 20UT Info Name: A	AAA	Display Up	ge before tap ↓ Down Operation Visual check	^	Displa	y after tap	Point	nter displace	ement Down	Data R M Ma	Lange Upr ax Return Er Allower Allower	per(90-104 rror wed 0.9 rror d(±) 0.9	2)% Others 6 0.60 6 0.60 8 0.30
erification N Standard 0.00 10.00 20.00 30.00 40.00 50.00 60.00 00 VUT Info Name: Au Model: Au	ormal Pre	ussure Gau Display Up	pe before tap ↓ Down Operation Visual check Zero positior	A Pass		y after tap Down Down Certificate No.	Poin • Ug • Ug	nter displace	ement Down 0	.00	Lange Upp ax Return Er Allovec Allowec	per(90-100 rror wed 0.9 rror d(±) 0.9	0)% Others 6 0.60 6 0.60 8 0.30
erification N Standard 0.00 10.00 20.00 30.00 40.00 50.00 60.00 DUT Info Name: AJ Number: AJ	ormal Pre	Display Up	pe before tap ↓ Down Operation Visual check Zero position Pointer offset	A Pass		y after tap Down Down Certificate No. Inspector Check Data 2021	Point	nter displace	ement Down 0	.00 9 6	Lange Upp ax Return Er Allovec Allowec	per(90-100 rror ved 0.9 rror d(±) 0.9	0)% Others 6 0.60 6 0.60 8 0.30
erification N Standard 0.00 10.00 20.00 30.00 40.00 50.00 50.00 00 VUT Info Name: AJ Model: AJ Number: AJ Gradet I	AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA	Display Up	Defore tap Down Down Operation Visual check Zero position Pointer offse Temperation	▲ ▲ ▲ ▲ ▲ ▲ ▲ ▲ ▲ ▲ ▲ ▲ ▲ ▲ ▲ ▲ ▲ ▲ ▲		y after tap Down Down Certificate No. Inspector Check Date 2022 Nett Date 2022	Point ↑ Up Point Po	Aumber Pad	ement Down 0 8 5	Data F M Ma .000	Lange Upp ax Return Er Allowec Allowec	per(90-100 rror (±) 0.9	0)% Others 6 0.60 6 0.60 8 0.30
erification N Standard 0.00 10.00 20.00 30.00 40.00 50.00 50.00 50.00 60.00 DUT Info Name: A Model: A Wumber: A Grade: 1 Unit: M	ormal Pre	Display Up	ge before tap ↓ Down ↓ Down		Displa Up	y after tap	Poin ▲ Up >styl-202110 (/10/ 9 2/ 4/ 8	Number Pad	ement Down 0 8 5 2	Data F M Ma .000	Lange Upp ax Return Ex Allower X Display Er Allower	per(90-100 rror rror (12) 0.9	0)% Others 6 0.60 6 0.60 8 0.30 8 0.30
erification N itandard 0.00 20.00 30.00 40.00 50.00 60.00 UTI Info Name: Al A Model: A Name: A Grade: 1 Unit: M	AAA Pa	ssure Gau Display Up	ge before tap ↓ Down ↓ Operation Visual check Zero positior Pointer offset Temperature Humidity Insulation Res	◆ Pass ● Pas	Displa Up	y after tap Down Down Certificate No. Inspector Check Date 2022 Remark	Poir ▲ UI Styl-202110 V(10/ 9 V/ 4/ 8	Aumber Pad	ement Down 0 8 5 2	Data F M Ma .00 9 6 3	Lange Upp ax Return Er Allowec Del Del	per(90-100 rror rror 0.9 0.4	0)% Others 6 0.60 8 0.30 8 0.30
Erification N Standard 0.00 10.00 20.00 40.00 50.00 60.00 UUT Info Name: A Model: A Number: A Unit: M	AAA Pa	ussure Gau Display Up	pe before tap ↓ Down ↓ Down	A A A A A A A A	Display	y after tap Down Certificate No. Inspector Check Date 2022 Remark	Poin ▲ Ur >styl-202110 V10/ 9 2/ 4/ 8	Number Pad	ement Down 0 8 5 2	Data R M Ma .00 9 6 3	Lange Upp ax Return Er Allowed Del OK	per(90-100 rror rror 0.4 0.4	2)% Others 6 0.60 8 0.30 8 0.30

7)After the verification of the indication value, the software will count the datas automatically and determine whether the tesed gauge is qualified or not. (while testing , if there are any data inputting errors, you can modify them by hand. and then click "calculation" to determine whether the tested gauge is qualified or not);

standard	Display	before tap	Displa	y after tap	Pointer disp	lacement	Data Range	% Others
	🛉 Up	🛉 Down	🛉 Up	🔶 Down	🛉 Up	🛉 Down	Max Beturn Error	
0.00	0.00	0.00	0.00	0.00			Allowed 0.96	0.60
10.00	10.00	10.00	10.00	10.00			Max Display Error	
20.00	20.00	20.00	20.00	20.00			Allowed(±) 0.96	0.60
30.00	30.00	30.00	30.00	30.00			Pointer displacement	
40.00	40.00	40.00	40.00	40.00			Allowed 0.48	0.30
50.00	50.00	50.00	50.00	50.00				
60.00	60.00	60.00	60.00	60.00				
DUT Info		Operation					Check Results	
Name: AA	A	Visual check	🖌 Pass 👻	Certificate No.	ptyl-202110-00001			Calculation
Model: AA	AA	Zero position	Pass V	Inspector			\overline{O}	
Number: AA	AAA	Pointer offset	Pass -	Check Date 202	1/10/11			Save Data
Grade: 1		Temperature	20 ℃	Next Date 202	2/ 4/10			
11 % Lm		Manual disc	50 QC	Domark	1		D.1. D.	
Standard	Display	before tap	Displa	y after tap	Pointer disp	lacement	Upper(90-100)	% Others
	↑ Up	V Down	🛉 Up	V Down	↑ Up	Y Down	Max Return Error	
0.00	0.00	0.00	0.00	0.00			Allowed 0.96	0.60
10.00	10.00	10.00	10.00	10.00			Max Display Error	
20.00	20.00	20.00	20.00	20.00			Allowed(±) 0.96	0.60
30.00	30.00	30.00	30.00	30.00			Pointer displacement	
40.00	40.00	40.00	40.00	40.00			Allowed 0.48	0.30
50.00	50.00	50.00	50.00	50.00				
60.00	60.00	60.00	60.00	60.00				
DUT Info		Operation				_	Check Results	
Name: AA	AA	Visual check	Pass -	Certificate No.	ptyl-202110-00002			Calculation
	AAA	Zero position	Pass v	Inspector			67	
Model: AA								
Model: AA	AAAA	Pointer offset	Pass +	Check Date 202	1/10/11			Save Data

8)After verification of indication value ,you need to input the appearance inspection, zero position,pointer offset stability, ambient temperature, relative humidity, verification date and next date for verification of the tested gauge in the interface of operation;

9)Click "save date", you can save the datas of the verification into the computer;

Eg2:Verification of pressure transmitter (same as flow transmitter)

1)Click "gauge management" and choose "pressure transmitter";

Query Uncheck Checked			0	Searc	h	Oper	ration	Mc	idify	Qelete 🧭	Check	Uiew	Export	Seturn]
Normal Pressure Gauge Pre	cision Pres	sure Gauge	Digital N	/lanom	neter Pr	essure	e Transmitte	er Pressu	re Switch Flow	w Transmitter		Selected 1			
Туре	Name	Model	Number	Unit	Grade	Div	Low-Limit	Hi-Limit	Check Points	Mandatory	Humidity	Temperature	Manufacturers	Department	Contact Pers
Normal Pressure Gauge	NP-Series	NP-01M	N000101	bar	1	0.05	0	60	7	1					
	ND 0 1	NP-01M	N000102	bar	1	0.05	0	60	7	1					

2) Choose the pressure transmitter to be tested, click "calibration";

uery Uncheck 💿 Che	cked		0,	Searc	h	peration	dd	dify	Delete	<u>C</u> heck	: <u>V</u> iew	Export	→ <u>R</u> eturn]
ormal Pressure Gau	ge Precision Pressu Select Standard Cali	re Gauge brator	Digital N	Aanom	neter Press	sure Trans	mitter Pressur	e Switch	Flow Transmitte	c	Selected 1	X	Department	Contact P
Normal Pressu	Name	Model	Number	Unit	Low Limit	Hi Limit	Manufacturer	Grage	Report Number	Media	Effective date			
, normal resse	😨 Digital Pressure	PR9120	P0001	bar	0	700	Paran	0.05	CNP202012001	Oil	2022-01-23			
Normal Pressu													-	
													-	
	Effective									\rightarrow	Next	X Cancel		
	Overdue									L				

3) Choose the standard gauge to be used (note that range of the selected standard gauge must

be consistent with that of the currently installed standard gauge).click "next";



4)Test system status, and click ok after confirmation;

5) Wait for about 10 seconds, the pressure is displayed as a non-zero state, click the "clear"

button of the standard device (PR9111 or PR9112);

Verification Digital Manometer

appear:

Standard	First	st	:	iecond		Maximum	Maximum	Forward Travel	Reverse Travel	Data Range		
	Forward	- Reverse	Forwa	rd 🗕	Revers	e Return Erro	r Return Error	Average	Average	Max Error		
0.0						2				Allowed(±)	0.005	
2.0						17				Max Return Error		
4.0										Allowed	0.005	
6.0												
8.0												
10.0						1						
DUT Info Name: D	M-Series	Opera Vis	ual check	🖌 Pass	•	Certificate No.	szyl-202110-	00001		Check Results	0	Automati
Model: D	M-10M 0001	,	Sealing	Pass	•	Inspector Check Date	2021/10/11			0		Calculatio
Grade: 0.	05	Tem	nperature	20	°C	Next Date	2022/10/10	•				<u>S</u> ave Dat
Unit: M	Pa	Insula	Humidity ation Res.	50 20	% ΜΩ	Remark						

6)Click"test automatically"the instrument pressure will rise automatically and it will record the

actual output value of the tested transmitter automatically.then the following interface will

S Verification Digital Manometer Standard First Second Data Range Forward Travel Reverse Travel Average Average Maximum Return Error Maximum Return Error - Forward - Reverse - Forward - Reverse Max Error 0.000 0.0 0 0 0 0 0.000 0.000 0.000 0.000 Allowed(±) 0.005 2.0 2 2 2 2 0.000 0.000 2.000 2.000 Max Return Error 0.000 4.0 4 4 4 4 0.000 0.000 4.000 4.000 Allowed 0.005 6.0 6 6 6 6 0.000 0.000 6.000 6.000 8.0 8 8 8 0.000 8.000 8.000 8 0.000 10.0 10 10 10 10 0.000 0.000 10.000 10.000 DUT Info Check Results Operation *STOP Name: DM-Series Visual check variation variatio variatio variatio variatio variatio variatio variatio variatio v szyl-202110-00001 ~ Sealing 🖌 Pass 🔻 Model: DM-10M Inspector Calculation Number: D0001 Insulation 🖌 Pass 👻 PASSED Check Date 2021/10/11 Temperature Grade: 0.05 20 Next Date 2022/10/10 °C Save Data 50 Meet Level 0.05 Humidity 96 Remark Unit: MPa 20 Insulation Res. MΩ

7)After verification of indication value, you need to input something into the interface of

operation, like appearance inspection, tightness, insulation strength, ambient

temperature, relative humidity, insulation resistance, verification date and next date for verification of the tested gauge;

8)Click "save date", you can save the datas of the verification into the computer;

Eg3:Calibration of pressure switches(electric connection point pressure gauge)

1) First connect the pressure switch to the SW,COM joints of the PR9112 intelligent pressure calibrator;

2)Click"gauge management", and then choose "pressure switch";

Query Ouncheck O Che	ecked				🔍 <u>S</u> ear	rch	Oper	ation Add	<u>M</u> odify	Dele	ete 🥡	Check	<u>V</u> iew	Export	• <u>R</u> eturn	
Iormal Pressure Ga	uge Precis	ion Press	ure Gauge	Digit	al Mano	meter	r Pressure	Transmitt	er Pressure S	witch Flow T	ransmitter	Sel	ected 1			
Туре	Name	Model	Number	Unit	Grade	Div	Low-Limit	Hi-Limit	Check Points	Mandatory	Humidity	Temperature	Manufacturers	Department	Contact Person	Conta
Pressure Switch	PS-Series	PS-06M	\$0001	MPa	1		0	6	7	1			Paran	Paran	Wang	010

3)Choose the pressure switch to be tested and then click"test";

Duery					0	Ineration										
● Uncheck ② Che	cked			Searc	:h		Jqq	Modify	Dele	nte 🧃	🤌 <u>C</u> hec	k 📃 <u>V</u> ier	w	Export	✤ <u>R</u> eturn	
Iormal Pressure Gau	uge Precision Pressu	ire Gauge	Digital I	Manom	neter Press	sure Tran	smitter P	ressure Swit	h Flow Ti	ransmitte	r	Selected 1				
Туре	Name Model	Number	Unit G	rade	Div Low-Li	mit Hi-L	imit Cheo	k Points M	andatory	Humidity	/ Temp	erature Manuf	acturers	Department	Contact Person	Conta
Pressure Swite	Select Standard Cal	ibrator	100% 1									- New York		x	Wang	010
	Name	Model	Number	Unit	Low Limit	Hi Limit	Manufac	turer Grag	e Report	Number	Media	Effective date				
	🗑 Digital Pressure	PR9120	P0001	bar	0	700	Paran	0.0	5 CNP202	012001	Oil	2022-0 <mark>1</mark> -23				
	🗊 Effective											N	~	C		
	📅 Overdue										2	Next	^	Lancei		
0		-	-	-	-	-	-		-		-		-			

4) Choose the standard gauge to be used (note that the range of the selected standard gauge

must be consistent with the range of the currently installed standard gauge).click "next";



5)Test system status, and click ok after confirmation;

6)Wait for about 10 seconds, the pressure is displayed as a non-zero state, click the "clear" button of the standard device (PR9111 or PR9112);

RUN	ADJUST	STABLE
\bigcirc	\bigcirc	\bigcirc
Current Pr	ressure	
	0000.0	3
		bar
Voltage: -	0.0003mA	SW Status
Switch :		OFF
Target Pre	ssure	
	0.0000	
		bar
\square	GTOD	\square
	STOP	-

7)After the instrument prompts" stable", click "test automatically";

ietting	Fi	st Switch	Secon	1 Switch		Three Swith	A	verage si	witching value	Set point	deviation	Data Range		
	🛉 Uj	v ∳ D	own 🛉 Up	🛉 Down	+	Up 🕴 Do	wn	🛉 Up	🛉 Down	🛉 Up	♦ Down	Set error		
												Allowed(±)	0.06	
2.0												Switch error		
												Allowed	0.6	
												Repetitive error		
4.0												Allowed	0.06	
UT Info Name: P	S-Series		Operation Visual che	ik 🖌 Pass	•	Certificate No	o. y	lkg-202	102-00001	Che	ck Results	Switch po	ints automatica omatic	lly
lumber: SC	0001		Temperatu	Pass 20	97	Check Dat	2021	/ 2/ 1			\bigcirc	🔜 Calc	ulation	
Grade: 1			Humidi Insulation Re	ty 50 s. 20	% ΜΩ	Next Dat	e 2022	2/2/1				💾 Sav	e Data	
0.112 04			Insulation Vo	lt 1500	v							🚍 <u>P</u>	rintout	

8)After one point is tested, there will be a prompt for next one, you can go on by hand;



9) After verification, the following interface will appear;

Setting	First Switch		Second S	Second Switch		Three Swith		Average switching value		t deviation	Data Range	
	🛉 Up	🛉 Down	🛉 Up	V Down	🛉 Up	V Down	u 🛉 Up	🛉 Down	🛉 Up	+ Down	Set error 0.00	
											Allowed(±) 1.00	
0.50	0.50	0.50	0.50	0.50	0.50	0.50	0.50	0.50	0.00	0.00	Switch error 0.00	
										Allowed 0.10		
0.80			0.80	0.80		80 0.80				Repetitive error 0.00		
	0.80	30 0.80			0.80		0.80	0.80 0.80	0.00	0.00	Allowed 1.00	
Model: PS-06M Number: S0001 Grade: 1 Unit: MPa			Clarity of mark Insulation Temperature Humidity	Pass Pass 20 50	• • • %	Inspector heck Date Next Date Remark	2021/10/11 2022/10/10	•	м	PASSED	Calculation	
				10								

10)After verification ,you need to input the appearance inspection, whether the logo clear or not ,insulation strength,ambient temperature,relative humidity, insulation resistance ,verification date and next date for verification of the tested gauge into the interface of operation;

11)Click "save date", you can save the datas of the verification into the computer;

VII.Routine maintenance

1.Oil pressure

1) Pay attention to the screen cleaning, clean up if it gets oily;

2) If the pressure outlet sealing ring is found to be damaged, it should be replaced in time;

3) The oil (water) cup will remain the impurities left during the verification of the meter being inspected. When the medium is turbid or there are too many impurities, clean the oil (water) cup in time and replace with a new working medium;

4) The liquid level of the oil (water) cup is below the lower limit, and new working medium should be added in time;

5) The pre-pressurization is repeatedly pressurized during pressurization, indicating that the equipment connecting pipes are all air, and the sewage and exhaust operations should be carried out;

6) The equipment should be operated at least 2-3 weeks to ensure the circulation of the medium.

2.Air pressure / micro pressure

1) If the pressure outlet sealing ring is found to be damaged, it should be replaced in time;

2) The equipment should be operated at least 2-3 weeks to ensure the normal operation of the equipment.